

Department of Transportation — Federal Aviation Administration
Supplemental Type Certificate

Number SA96SW

This certificate, issued to ALCOR, Inc.
 10130 Jones-Maltsberger Road
 San Antonio, Texas 78284

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3, 4a, 4b of the Civil Air Regulations, and Part 23 of the Federal Aviation Regulations.

Original Product — Type Certificate Number: See Limitations and Conditions
 Make: See Limitations and Conditions
 Model: See Limitations and Conditions

Description of Type Design Change:

Installation of ALCOR Mixture Control Indicator Kits, or Exhaust Gas Temperature Indicator Kits.

Limitations and Conditions:

1. Mixture Control Indicator Kit No. SE per Report 62-83 and No. TE per Report 62-85 eligible for installation in aircraft included on FAA Approved List dated 8/23/83, or later FAA approved list.
2. Exhaust Gas Temperature Indicator Kit Nos. 225, 225TR per Report 68-144 and Kit Nos. 326, 326TR, 325DS, 325DSTR, 325SS, and 325SSTR per Report 68-145 eligible for installation in aircraft included on FAA Approved List dated 8/23/83, or later FAA approved list.
3. Compatibility of this modification with other previously approved modifications must be determined by the installer.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 10, 1962

Date of issuance: August 17, 1962

Date issued: 12/7/62; 2/15/63; 7/2/63; 8/9/63;
 12/9/63; 6/19/64; 7/20/64; 9/20/64;
 10/5/64; 5/5/65; 6/26/67; 4/15/68; 4/27/70;
 5/14/73; 11/1/74; 4/6/76; 4/26/77; 10/1/81;
 Date amended: 8/23/83 Revision 19



By direction of the Administrator
(Signature)

for Don P. Watson
 Manager, Aircraft Certification Division
 Southwest Region

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.